

neath the wing and insert wires. See drawing.

Many model makers prefer to finish their models in natural wood finish, using either shellac or clear lacquer. If you wish to paint your model in the regular Bell Airacuda color use aluminum paint. You

can also show windows, openings, ailerons, landing flaps, elevators, etc., by drawing these with pen and ink. See drawings. Use only India drawing ink as other inks may rub off.

Put shields and insignia on last. See photograph on carton.

